




***Caution: Please read all instructions carefully before starting the assembly process. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and ensure the parts are not damaged during the assembly.

Code	Parts List		
1	China Hutch		1Pc
2	China Base		1Pc
3	Right Glass		2Pcs
4	Left Glass		2Pcs


Step	Code	Hardware List		
3	A	Iron -plate		2Pcs
3	B	Allen Bolt - Ø1/4x20x19mm		4Pcs
		Flat washer - Ø1/4x19x1.5mm		4Pcs
		Lock washer - Ø1/4		4Pcs
3	C	Allen Key - 4mm		1Pc
4	D	Furniture Tipping Restraint		1Set

TOOLS REQUIRED (NOT PROVIDED)

Description	Sketch
Phillips screwdriver	




STEP 1




***Caution: Please read all instructions carefully before starting the assembly process. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and ensure the parts are not damaged during the assembly.

STEP 2



STEP 3



***Caution: Please read all instructions carefully before starting the assembly process. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and ensure the parts are not damaged during the assembly.

STEP 4

