




# Assembly Instructions BHOD 1022 Group

SKU#'s	
10140224	10140248
10340228	10240240
10240226	10340242
10440220	10440244
10940220	10640248
	10940244

## LEG ASSEMBLY


**Step 1** - Working on a clean surface, turn the unit on its back with the base facing your work area. Position the leg as shown, approximately 1/4" from outside edges of bottom surface.



**Parts List:**  
(A) Tri Leg x 4  
(B) 2" Phillips head screw x 8

**Tools Required:**  
Phillips Head Screwdriver

**Step 2** - Fasten the leg by inserting (2) - 2 inch screws per leg in the holes provided and screw until the leg is secure.



Repeat steps 1 and 2 for the remaining legs. Turn the unit upright and place in the desired location.