




Assembly Instructions BHOD 1125 Group

SKU#'s		
10131251	10711580	10311582
10231253	10711592	10411584
10331255	10511586	10111588
10431257		
10531259	10211580	
10631251	14211267	
10931257		

LEG ASSEMBLY

Step 1 - Working on a clean surface, turn the unit on its back with the base facing your work area. Position the leg as shown, approximately 1/4" from outside edges of bottom surface.



Parts List:


(A) 4" x 4" Leg x 4

(B) 2" Phillips head screw x 8
(pictured below)

Tools Required:

Phillips Head Screwdriver

Step 2 - Fasten the leg by inserting (2) - 3 inch screws per leg in the holes provided and screw until the leg is secure.



Screws:



Repeat steps 1 and 2 for the remaining legs. Turn the unit upright and place in the desired location.