




Assembly Instructions BHOD 3480 Group

SKU#'s
12234819 12234807
12134817 12134805
12334809 12134502
12434801

LEG ASSEMBLY

Step 1 - Working on a clean surface, turn the unit on its back with the base facing your work area. Position the leg as shown, approximately 2.5" from outside edges of bottom surface.



Parts List:
(A) 1.5" Round Leg x 4
(B) 2" Phillips head screw x 4 (pictured below)
Tools Required:
Phillips Head Screwdriver

Step 2- Fasten each leg by inserting the provided screw and tightening until the leg is secure. Repeat steps for each leg.

