


Assembly Instructions BHOD 3030 Group

SKU#'s


12130302 12330306 12430308 12430409	12530300 12830306 12730304 12630302 12230405 12130403	12730403 12630403 12830403 12330403
12430409 12530401		

LEG ASSEMBLY

Step 1 - Working on a clean surface, turn the unit on its back with the base facing your work area. Position the leg as shown, approximately 1/4" from outside edges of bottom surface.



Step 2 – Fasten the leg by inserting (2) – 2 inch screws per leg in the holes provided and screw until the leg is secure.



Repeat steps 1 and 2 for the remaining legs. Turn the unit upright and place in the desired location.



