ASSEMBLY INSTRUCTIONS

ITEM NO:55625

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment. (Note: Loosely thread all screws/bolts first. Once the item is assembled then completely tighten.)

PARTS LIST				HARDWARE LIST				
NO.	Description	Sketch	Quantity	NO.	Description	Sketch	Size	Quantity
Α	Тор		1	D	Blots		Ф1/5 " *1/2 "	16
В	Legs		2	Е	Blots	6	3/25 "	4
С	Irons		2	F	Allen wrench		Ф4/25 "	1



STEP TWO:





