





Assembly Instructions

1268MC



Parts List

lable	Picture	Description	Qty
A			1
B			4
C			4

Hardware List

lable	Picture	Description	Size	Qty
H-1		Bolt	M6X15 mm	16
H-2		Bolt	M6X40 mm	8

Tool List


lable	Picture	Description	Qty
T-1		Allen Key	1

Assembly Steps

ATTENTION:

DO NOT COMPLETELY TIGHTEN ANY SCREWS UNTIL ALL PARTS ARE IN PLACE

Step 1



Step 2

