## COAST TO COAST IMPORTS, LLC

## Assembly Instructions ITEM NO.:30511

Thank you for purchasing this quality product. Be sure to check all packingmaterial carefully for small parts that may have come loose inside the carton during shipment. (Note: Loosely thread all screws/bolts first. Once the item is assembled then completely tighten.)

	PARTS LIST:				HARDWARE LIST					
	NO.	Description	Sketch	Quality	NO.	Sketch	Description	Side	Quality	
	A	Тор		1pc	D	0	Blots	Ø5/16"*1-5/8"	8pcs	
					Е	0	Flast washer	Ø5/16"*1/2"	8pcs	
	В	Legs		4pcs	F		Look washer	Ø5/16"*3/4"	8pcs	
					G		Allen wrench	M5*65L	1pc	



