ASSEMBLY INSTRUCTIONS ITEM NO.:55641

Thank you for purchasing this quality product. Be sure to check all packingmaterial carefully for small parts that may have come loose inside the carton during shipment. (Note: Loosely thread all screws/bolts first. Once the item is assembled then completely tighten.)

une	ad all screws/bo	oits first. Once	e the item is	asse	mblea the	en completei	iy ugnten.)		
PARTS LIST:					HARDWARE LIST:				
NO.	Description	Sketch	Quantity	NO.	Sketch	Description	Size	Quantity	
Α	Тор		1	F	9	Blots	Ø1/4"*1-3/8"L	6	
В	Right Leg	, D	1	- G		Flast washer	Ø1/4"	18	
С	Left Leg	,	1	H		Look washer	Ø1/4"*3/4"	18	
	Bese-Metal	7	1	K L		Allen wrench Blots	M4*65L Ø1/4"*1/2"L	8	
E	Bese-Metal		2	N		Blots	Ø1/4"*1"L	4	
					G H B B				
	D B	C E A	K L G H			A	djustable leveler		