
Assembly Manual

Α	00 00	1PC	В		1PC	С		1PC
D		2PCS	E	<u>a</u>	4PCS	F	_	1PC
G	0	12PCS	н	I	12PCS			

Step 1:Lay Part A with holes facing up on flat surface



Step 4: Parts E screw to Part B using Part F, Parts G and Parts H



Step 5: Put Part C on the top of Part A