



UTTERMOST

**Item#23373**


**Parts list**

Top Assembly	1 pc
Leg base	2 pc
cross metal bar	1 pc

**Assembly Instruction**

**Hardware list**

Screw	4 pcs
Nut	4 pcs
Spanner	1 pc
Allen wrench	1 pc



1. Take all parts out of the carton carefully and place on a clean flat surface.
2. Screw the legs into top as illustrated A and B with screws .
3. Screw the cross metal bar as illustrated C with Nuts .
4. Use spanner and allen wrench to secure tightly. Then turn right side up.
5. Assembly is complete.