



***Caution: Please read all instruction carefully before starting the assembly process. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and ensure the parts are not damaged during the assembly.

Code	Parts List		
A	SERVER		1 PC

Step	Code	Hardware List		
1	#1	Tipping Restraint		1 SET

TOOLS REQUIRED (NOT PROVIDED)	
Description	Sketch
Phillips screwdriver	