

Assembly Instructions





STEP 1:Attach the base frame to one side leg by using bolts(B)&washers(C&D)& Alllen wrench(E).Then Cover the plastic Cap(F)on the bolt(B).





STEP 4:Attach the top to the side legs by bolt(A)&Washers(C&D).






HARDWARE LIST

NO.	Drawing	Part Size	Q'ty
Α	@	Ø5/16"*2"L Bolt	12pcs
В	00000C	Ø5/16"*1-1/2"L Bolt	4pcs
С	0	Ø5/16" Spring Washer	12pcs
D	0	Ø5/16"*Ø3/4" Flat Washer	16pcs
Е	_	4mm Allen wrench	1pc
F	0	Ø25*9mm Plastic Cap	4pcs
G	02000	Ø8*30mmL Wood Dowel	8pcs


Assembly Instructions



MODEL:1302-9C


screw the bolts tightly.

Assembly Instructions



One person applies pressure to hold left/right legs and STEP 3:Tigh stretchers together, and the other one screws up the stretcher.


 $\begin{tabular}{ll} \textbf{STEP 3:} Tighten up those loose bolts in Step 1. \\ \end{tabular}$




HARDWARE LIST

NO.	Drawing	Part Size	Q'ty			
Α	@	Ø5/16"*51mmL Bolt	4pcs			
В	0	Ø5/16" Spring Washer	4pcs			
С	0	Ø5/16"*19mL Flat Washer	4pcs			
D	Dumm	#8*45mmL Screw	4pcs			
Е	_	4mm Allen wrench	1pc			
F	GLUE	GLUE	1pc			

Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts that may have come loose inside the carton during shipment. ***Caution:Please read all instructions carefully before starting the assembly process.







NO.	Drawing	Part Size	Q'ty
A	-	Ø5/16"*1-1/2"L Bolt	12pcs
В	0	Ø5/16" Spring Washer	12pcs
С	0	Ø5/16"*Ø3/4" Flat Washer	12pcs
D	_	4mm Allen wrench	1pc
Е	02000	Ø10*30mmL Wood Dowel	8pcs