

SUNNY SYPR 7780 COSTA MESA COFFEE TABLE


Manufactured for Rooms To Go

SKU:73077882

Version 1.0 12/2024

No.	PARTS LIST		QTY
Α	ТОР		1
В	SHELF	0	1
С	LEG		4

No.	HARDWARE PACK		QTY
AA	(a)	BOLT 1/4"-23 x 25mm	12
ВВ	0	WASHER 1/4"	12
СС		ALLEN KEY	1
DD	0	CAP 1/4"	12



Hardware Pack Location(s): Bottom of the shelter panel.

COSTA MESA COFFEE TABLE, 73077882




SUNNY SYPR 7780 COSTA MESA COFFEE TABLE

Manufactured for Rooms To Go


SKU:73077882

Version 1.0 12/2024

***Caution: Please read this instruction carefully before starting the assembly process, make sure all parts are present. Do not completely fasten each screw until all the bolts are properly fixed. These parts are cumbersome and heavy, 2 person assembly is recommended in order to prevent personal injury and parts damage.



Attach the table leg (C) to the table top (A) with bolts and washers.



Attach the table shelter (B) to the table leg (C) with bolts and washers.




SUNNY SYPR 7780 COSTA MESA COFFEE TABLE

Manufactured for Rooms To Go

SKU:73077882

Version 1.0 12/2024

***Caution: Please read this instruction carefully before starting the assembly process, make sure all parts are present. Do not completely fasten each screw until all the bolts are properly fixed. These parts are cumbersome and heavy, 2 person assembly is recommended in order to prevent personal injury and parts damage.



Adjust the foot leveler. Assembly complete.



SUNNY SYPR 7780 COSTA MESA COFFEE TABLE

Manufactured for Rooms To Go

SKU:73077882

Version 1.0 12/2024

IMPORTANT SAFETY INSTRUCTIONS

When using furnishing, basic precautions should always be followed, including the following: Read all instructions before using (this furnishing).

To reduce the risk of injury to persons:

- 1. Close supervision is necessary when this furnishing is used by, or near children, or disabled persons, if applicable.
- 2. Use this furnishing only for its intended use as described in these instructions. Do not use attachments not recommended by the manufacturer.