


Assembly Instructions BHOD 3140 Group

SKU#'s


12331601 12431502 12231609 12231508 12131607 12331500 12331500 12131506 12531605 12531504 12631607 12631506

LEG ASSEMBLY

Step 1 - Working on a clean surface, turn the unit on its back with the base facing your work area. Position the leg as shown, approximately 1/4" from outside edges of bottom surface.



Step 2 – Fasten the leg by inserting (2) – 2 inch screws per leg in the holes provided and screw until the leg is secure.



Repeat steps 1 and 2 for the remaining legs. Turn the unit upright and place in the desired location.