ASSEMBLY INSTRUCTIONS

ITEM NO:60237&60242

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.(Note:Loosely thread all screws/ bolts first. Once the item is assembled then completely tighten.)

HARDWARE LIST

PARTS LIST

NO.	Description	Sketch	Quantity	NO.	Description	Sketch	Size	Quantity
Α	Тор		1	D	Look washer		Ф1/5 " * 1/50 "	8
В	Legs		2	Е	Blots		Ф7/25 "* 8/5 "	6
				F	Blots		Ф7/25 "* 2 "	2
С	Board		1	G	Block Shot		Ф3/5 ″	2
				Н	Allen wrench		Ф1/5 ″	1
STEP ONE: STEP TWO:								
B H E D A A								
STE	EP TRHEE:			s	TEP FOUR:	А	нір	
		H FDA B		- G				