

## ASSEMBLY INSTRUCTIONS

ITEM NO: 60239

Thank you for purchasing this quality product.Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.(Note:Loosely thread all screws/bolts first.Once the item is assembled then completely tighten.)

bolts first.Once the item is assembled then completely tighten.)									
PARTS LIST					HARDWARE LIST				
NO.	Description	Sketch	Quantity	NO.	Description	Sketch	Size	Quantity	
Α	Тор		1	D	Look washer		Ф1/5 " * 1/50 "	4	
В	Legs		1	Е	Blots		Ф7/25 "* 8/5 "	4	
	-	2 6		F	Allen wrench		Ф1/5 ″	1	
С	Board		1			3004			
STEP ONE:					STEP TWO:				





## STEP TRHEE:

