
ASSEMBLY INSTRUCTIONS

ITEM NO: 60240&60244


Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment. (Note: Loosely thread all screws/bolts first. Once the item is assembled then completely tighten.)

PARTS LIST				HARDWARE LIST				
NO.	Description	Sketch	Quantity	NO.	Description	Sketch	Size	Quantity
Α	Тор		1	D	Look washer		Ф1/5 " * 1/50 "	2
В	Legs		1	Е	Blots		Φ7/25 "* 8/5 "	2
				F	Allen wrench		Ф1/5 ″	1
С	Board		1		•			

STEP ONE:



STEP TWO:



STEP TRHEE:

