COAST TO COAST IMPORTS, LLC

ASSEMBLY INSTRUCTION

ITEM NO · 91740

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment. (Note: Loosely thread all screws/bolts first. Once the item


DADT LICT

PART	LIST	
PART#	IMAGE	QTY
Α	0	8
В	™	8
С		1

is assembled then completely tighten.)

CODE	PARTS	QTY
1		1
2	4	4
3		1
4	#	1

STEP ONE.



STEP TWO:



STEP THREE.



STEP FOUR:

