


General Assembly Guidelines


- I. Ensure that all parts and hardware are available before beginning assembly.
- II. Follow each step carefully to ensure the proper assembly of this product.
- III. Two people are recommended for ease in the assembly of this product.
- IV. The three main types of hardware used to assemble this product are : wood dowels , screws and bolts.
- V. The provided glue is to secure wood dowels in place . When first inserting dowels , locate the appropriate hole for the dowel , place a small amount of glue in the hole and insert the dowel . Wipe away excess glue immediately.




In future assembly steps when dowels are necessary to attach assembly parts together , place a small amount of glue on the end of the dowel before attaching parts together . Wipe away excess glue immediately.




VI. A Phillips head screwdriver is required for the assembly of this product .




VII. Power tools should not be used to assemble this product .






Hardware List


| А | | Ø12x40mm | Wooden dowel | 4 | pcs |
|---|--|----------|--------------|---|-----|
| В | (C) DDDD | Ø5x12 | Screw | 8 | pcs |
| С | <a (x)<="" current="" td=""><td>Ø3x15</td><td>Screw</td><td>8</td><td>pcs</td> | Ø3x15 | Screw | 8 | pcs |
| D | () () | | Bracket | 4 | pcs |
| Е | and the second sec | Ø8x60mm | Bolt | 4 | pcs |
| F | | Ø5/16 | Washer | 4 | pcs |
| G | Ì | Ø5/16 | Nut | 4 | pcs |
| Н | 2 | Ø5/16 | Wrench | 1 | pcs |
| J | \bigcirc | Ø38mm | Sticker | 4 | pcs |
| К | | | Glue tube | 1 | pcs |





Philips head screwdriver required for assembly (not included)

The hardware quantities listed above are required for proper assembly. Some extra hardware may also have been included.









Copyright @ 2018, by Walker Edison Furniture Co., LLC. All rights reserved.