








Step	Code	Hardware		Q'TY
	A	Allen key M4		1 Pc

PARTS LIST



1. Table Top - 1 Pc

2. Left Metal Legs - 2 Pcs

3. Right Metal Legs - 2 Pcs

4. Metal Stretcher - 1 Pc



\*\*\*Cautions: Please read all instructions carefully before starting the assembly process. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and ensure the parts are not damaged during the assembly.



\*\*\*Cautions: Please read all instructions carefully before starting the assembly process. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and ensure the parts are not damaged during the assembly.



All allen bolts are already attached to the table top, with 3 mm gaps.

