



Assembly Manual




(A)

x1

(B)


x4

1



Step 1: Lay Part A with holes facing up on flat surface

2



Step 2: Parts B screw to Part A

3

