
## **ASSEMBLY INSTRUCTION**

	NO	PART	QTY		STEP 1 Please open	
	1	Balland	HEABOARD	1PC		assembly by Cushion (1) (F), 3 Flat W
	2	[]	HEADBOARD LEG WITH LABEL "R"	1PC		
	3	( <u></u>	HEADBOARD LEG WITH LABEL "L"	1PC		
	4	Į.	WING (R)	1PC		
	5		WING (L)	1PC		
	6		FOOTBOARD	1PC		•
	7	J I	FOOTBOARD LEG	2PCS		
	8		SIDE RAIL	2PCS		
	9	[	SIDE RAIL	2PCS		
	10		SIDE RAIL LEG	2PCS		
	11		SLAT	4PCS		OTED 2
	12	WITH WITH	SUPPORT LEG I ADJUSTABLE FEET	4PCS		STEP 3 Attach the pr with 2 Screw
I	ITEM HARDWARE			QTY	with 2 Serew	
	А	0)000	JCBB SCREW M8 x 20MM	8PCS		
	В		JCBC SCREW M6 x 15MM	6PCS		
	С		JCBC SCREW M6 x 25MM	8PCS		
	D		JCBC SCREW M6 x 35MM	12PCS		
	Е		JCBC SCREW M6 x 60MM	2PCS		
	F	0	PANHEAD M4 x 38MM	4PCS		
	G	()	SCREW M4 x 32MM	8PCS		
	Н		RING WASHER M6 x 12MM	18PCS		
	Ι		FLAT WASHER M6 x 19MM	18PCS		
	J		IVI4 X 05IVIIVI	1PC		
	Κ		L - KEY M5 x 65MM	1PC		



3 J


2

4

3

D H


Attach each wing (4) & (5) to each side of Headboard Cushion (1) by aligning the hole and securing with 1 Allen Bolt (D), 1 Allen bolt (E), 2 Spring Washer (H), 2 Flat Washer (I) per side using L-key (J).



# **ASSEMBLY INSTRUCTION**


#### STEP 5

Attach each Footboard Legs (7) to the bottom of the Footboard Cushion (6) by securing with 3 Allen Bolts (B) per leg using L-Key (J).



### STEP 7

Attach Side Rail to the Headboard Leg (2) & (3) & Footboard Cushion (6). Aligning holes and securing with 2 Allen Bolts (A) per each and using L-Key (K).



### STEP 6

Attach Support Legs (12) to Slat (11) by securing with 1 Allen Bolt (D) per support leg using L-Key (I).

