











Step	Code	Hardware		Q'ty
1	A	Hex-Bolt 6.3x30, P-SPA, SS, Head Ø11 (1/4"-20)		04 pcs
2	B	Hex-Bolt 6.3x20, P-SPA, SS, Head Ø11 (1/4"-20)		04 pcs
1,2	C	Plain Washer 6.5x16x1, SS		08 pcs
3	D	Bolt Cap 13.6 x 6.8 PL		08 pcs
1,2,3	E	Spanner 1/4"		01 pc



Step	Code	Component		Q'ty
1	F	Table Top Frame		01 pc
1	G	Leg Frame		02 pcs
2	H	Support Leg Frame		01 pc


**\*\*\*Caution:** Please read all instructions carefully before starting the assembly process. Always place parts on a flat surface lined with an anti-scratch fabric. These parts are cumbersome and heavy. Therefore, two people are recommended in order to prevent personal injury and insure the parts are not damaged during the assembly.

## STEP 1




Attach the Leg Frame (G) to the below of the Table Top Frame (F) with the Hex-Bolt (A), Plain Washer (C). Tighten with Spanner (E) to 80% tightness

## STEP 2



Attach the Support Leg Frame (H) to the Leg Frame (G) with the Hex-Bolt (B), Plain Washer (C). Tighten with Spanner (E) to 80% tightness.

## STEP 3



Tighten 100% tightness all positions.

Attach Bolt Cap (D) on the Hex- Bolt. Then turn the table upright.

Assembling Completed.