

Assembly Instructions

Identify All Parts Packed In The Carton Against The Parts List. Remove All Protective Materials. Place Parts On A Non-abrasive Surface To Avoid Scratching. Do Not Attempt Assembly If Any Parts Are Missing Or Damaged.


Warning:Please Do Not Use Acid Or Alkaline Washing Liquid To Clean The Product.

Assemble The Product As Below Show Step By Step.

Part List

NO.	SKETCH	DESCRIPTION	QTY	NO.	SKETCH	DESCRIPTION	QTY
Α		Leg	4	AA		Bolt (M6*20)	12
В		Table Top	1	ВВ		Wrench	1
С	8	Foot Glider	4				

STEP 1
Hand tighten nuts 3-4 revolutions only, after attached all the bolts, adjust all the part at correct position, then tighten all the bolts and Nuts.do not over tighten.



JWUA GL2AQ-42421-145 Made in China