



# Assembly Manual



Step 1: Lay Part A with holes facing up on the flat surface.



Step 2: Parts C screw to Part A using Parts F and Part G.




A	B	C	D
1PC	2PCS	4PCS	1PC



E	F	G	
1PC	12PCS	1PC	

Step 3: Parts B screw to Parts C using Parts F and Part G.



Step 4: Part E screws to Part D and then insert Part D into Part A.

