








Thank you for purchasing this quality product. Be sure to check all the packing material carefully for small parts, which may have come loose inside the carton during shipment. Identify and count all parts and compare with the HARDWARE LIST below.




Step 1



Step 2

| NO TOOLS REQUIRED | | | |
|-------------------|-------------|--|-----|
| PARTS LIST | | | |
| NO. | DESCRIPTION | PARTS | QTY |
| A | Armrests |  | 2 |
| B | Trunk |  | 1 |
| C | Base |  | 1 |
| D | Screws |  M6*60mm | 4 |
| E | Allen Key |  M6 | 1 |



Step 3

Hardware Pack Location:
In the corner of inside carton